



Таблица за преобразуване на налягане

PSI	MPa	kG/cm2	bar	atm
25	0,17	1,76	1,72	1,70
50	0,34	3,52	3,45	3,40
75	0,52	5,27	5,18	5,10
100	0,69	7,03	6,90	6,80
200	1,32	14,06	13,80	13,60
300	2,07	21,09	20,70	20,40
400	2,76	28,12	27,60	27,20
500	3,45	35,15	34,50	34,00
600	4,14	42,18	41,40	40,80
700	4,83	49,21	48,30	47,60
800	5,52	56,24	55,20	54,40
900	6,20	63,28	62,10	61,20
1000	6,90	70,31	69,00	68,00
1100	7,58	77,34	75,90	74,80
1200	8,27	84,37	82,80	81,60
1300	8,96	91,40	89,70	88,40
1400	9,65	98,43	96,60	95,20
1500	10,34	105,46	103,50	102,00
1600	11,03	112,49	110,40	108,80
1700	11,72	119,52	117,30	115,60
1800	12,41	126,55	124,20	122,40
1900	13,10	133,58	131,10	129,20
2000	13,79	140,61	138,00	136,00



2100	14,48	147,64	144,90	142,80
2200	15,17	154,68	151,80	149,60
2300	15,86	161,71	158,70	156,40
2400	16,55	168,74	165,60	163,20
2500	17,24	175,77	172,50	170,00
2600	17,93	182,80	179,40	176,80
2700	18,62	189,83	186,30	183,60
2800	19,30	196,86	193,20	190,40
2900	19,99	203,89	200,10	197,20
3000	20,68	210,92	207,00	204,00
3100	21,37	217,95	213,90	210,80
3200	22,06	224,98	220,80	217,60
3300	22,75	232,01	227,70	224,40
3400	23,44	239,04	234,60	231,20
3500	24,13	246,07	241,50	238,00
3600	24,82	253,10	248,40	244,80
3700	25,51	260,14	255,30	251,60
3800	26,20	267,17	262,20	258,40
3900	26,89	274,20	269,10	265,20
4000	27,58	281,23	276,00	272,00
4100	28,27	288,26	282,90	278,80
4200	28,96	295,29	289,80	285,60
4300	29,65	302,32	296,70	292,40
4400	30,34	309,35	303,60	299,20
4500	31,03	316,38	310,50	306,00
4600	31,72	323,41	317,40	312,80



4700	32,41	330,44	324,30	319,60
4800	33,10	337,47	331,20	326,40
4900	33,78	344,50	338,10	333,20
5000	34,47	351,54	345,00	340,00
5100	35,16	358,57	351,90	346,80
5200	35,85	365,60	358,80	353,60
5300	36,54	372,63	365,70	360,40
5400	37,23	379,66	372,60	367,20
5500	37,92	386,69	379,50	374,00
5600	38,61	393,72	386,40	380,80
5700	39,30	400,75	393,30	387,60
5800	39,99	407,78	400,20	394,40
5900	40,68	414,81	407,10	401,20
6000	41,37	421,84	414,00	408,00
6100	42,06	428,87	420,90	414,80
6200	42,75	435,90	427,80	421,60
6300	43,44	442,93	434,70	428,40
6400	44,13	449,96	441,60	435,20
6500	44,82	457,00	448,50	442,00
6600	45,51	464,03	455,40	448,80
6700	46,20	471,06	462,30	455,60
6800	46,88	478,09	469,20	462,40
6900	47,57	485,12	476,10	469,20
7000	48,26	492,15	483,00	476,00
7100	48,95	499,18	489,90	482,80
7200	49,64	506,21	496,80	489,60



7300	50,33	513,24	503,70	496,40
7400	51,02	520,27	510,60	503,20
7500	51,71	527,30	517,50	501,00
7600	52,40	534,33	524,40	516,80
7700	53,09	541,36	531,30	523,60
7800	53,78	548,39	538,20	530,40
7900	54,47	555,42	545,10	537,20
8000	55,16	562,46	552,00	544,00
8100	55,85	569,49	558,90	550,80
8200	56,54	576,52	565,80	557,60
8300	57,23	583,55	572,70	564,40
8400	57,92	590,58	579,60	571,20
8500	58,61	597,61	586,50	578,00
8600	59,30	604,64	593,40	584,80
8700	59,98	611,67	600,30	591,60
8800	60,67	618,70	607,20	598,40
8900	61,36	625,73	614,10	605,20
9000	62,05	632,76	621,00	612,00
9100	32,74	639,79	627,90	618,80
9200	63,43	646,82	634,80	625,60
9300	64,12	653,86	641,70	632,40
9400	64,81	660,89	648,60	639,20
9500	65,50	667,92	655,50	646,00
9600	66,19	674,95	662,40	652,80
9700	66,88	681,98	669,30	659,60
9800	67,57	689,01	676,20	666,40



9900	68,26	696,04	683,10	673,20
10000	68,95	703,07	690,00	680,00
11000	75,84	773,38	759,00	748,00
12000	82,74	843,68	828,00	816,00
13000	89,63	913,99	897,00	884,00
14000	96,53	984,30	966,00	952,00
15000	103,42	1054,60	1035,00	1020,00